

**Field Safety Notice**  
**FSN2020-02****URGENT MEDICAL DEVICE FIELD SAFETY NOTICE – IMMEDIATE ACTION REQUIRED**  
**EliA Stool Extraction Kit and EliA Stool Extraction Kit 2**

Dear Customer,

The purpose of this letter is to advise you that Phadia AB, part of Thermo Fisher Scientific, is issuing a Field Safety Notification for:

Product	Material number	Affected lot number
EliA Stool Extraction Kit	14-5638-01	0236, 0237 and 0238
EliA Stool Extraction Kit 2	14-5651-01	0293, 0295, 0299, 0300, 0301, 0302, 0303, 0304, 0305, 0306, 0307 and 0309

**REASON FOR VOLUNTARY RECALL/FIELD SAFETY NOTICE:**

One customer complaint has been reported where EliA Stool Extraction Kit 2 had only three instead of four notches on the dipstick rod.

Investigation showed that there could be other error modes such as missing or broken dipstick rods as well as missing notches. If a broken dipstick rod in EliA Stool Extraction Kit or EliA Stool Extraction Kit 2 is used for stool sampling, it may lead to falsely low or negative results.

- 1 missing notch may lead to falsely negative results between 37mg/kg and 50mg/kg.
- 2 missing notches may lead to falsely negative results between 25mg/kg and 50mg/kg.
- 3 missing notches may lead to falsely negative results between 12,5 mg/kg and 50mg/kg.

There have been no reports of adverse events as a result of a broken dip stick rod in the EliA Stool Extraction Kit 2.

**RISK TO HEALTH:**

In case of falsely low or negative results for fecal calprotectin, the physician may erroneously believe the patient has functional and not inflammatory bowel disease. This could lead to a delayed diagnosis of symptomatic chronic disease. A delay in diagnosis and prolonged suffering from chronic disease may cause reversible injury, however the probability for harm caused by falsely low or negative fecal calprotectin results is remote.

**ACTIONS TO BE TAKEN BY THE CUSTOMER:**

- Please ensure that the dipstick rod for the affected lots of EliA Stool Extraction Kit or EliA Stool Extraction Kit 2 has four notches before use.
- Please scrap or return any broken dipstick rod and order a replacement product for free of charge.
- Please assess the test results from affected lots of EliA Stool Extraction Kit or EliA Stool Extraction Kit 2 and determine if retesting of samples is needed according to your internal operating procedures. All positive results  $\geq 50$  mg/kg can be considered as true positive.

**TYPE OF ACTION BY THE MANUFACTURER:**

- Corrective and preventive actions (CAPA) have been initiated to prevent this from recurring.

We appreciate your immediate attention to this field correction. By returning the attached Acknowledgment Form you will facilitate our reporting of this matter to the appropriate Regulatory Authorities. We apologize for any inconvenience this may have caused and appreciate your understanding as we take action to ensure customer safety and satisfaction.

If you have any questions, please contact:

Area Manager Jari Siuro (+358 400 304750; jari.siuro@thermofisher.com) or Sales & Application Specialist Hannakaisa Jaatinen (+358 40 769 0290; hannakaisa.jaatinen@thermofisher.com).

We apologize for any inconvenience this may cause.

Sincerely,

Josefina Alander

Sales Manager

ImmunoDiagnostics

Thermo Fisher Scientific

Thermo Fisher Diagnostics Oy

Ratastie 2 | FI-01620 Vantaa, Finland

Mobile +358 50 3090 189 | Phone office +358 10 3292 117 | Fax +358 10 3292 531

josefina.alander@thermofisher.com | www.thermoscientific.com/phadia

**MEDICAL DEVICE FIELD SAFETY NOTICE RETURN RESPONSE**

**Acknowledgment & Receipt Form  
Response Required**

**EliA Stool Extraction Kit and EliA Stool Extraction Kit 2**

I have read and understand the information in the attached FSN2020-02 \_\_\_\_\_ (initials)

Any adverse events associated with the recalled product? \_\_\_\_\_ Yes \_\_\_\_\_ No

If yes, please explain:

\_\_\_\_\_

**AFFECTED PRODUCT INFORMATION:**

Product	Material number	Affected lot number
EliA Stool Extraction Kit	14-5638-01	0236, 0237 and 0238
EliA Stool Extraction Kit 2	14-5651-01	0293, 0295, 0299, 0300, 0301, 0302, 0303, 0304, 0305, 0306, 0307 and 0309

Use additional sheet(s) if necessary.

**RETURN RESPONSE (please provide additional information, if applicable):**

Date: \_\_\_\_\_

Signature: \_\_\_\_\_

(Please print name): \_\_\_\_\_

Name of Laboratory: \_\_\_\_\_

**E-mail a signed, scanned copy or fax to:**

Thermo Fisher Scientific  
Thermo Fisher Diagnostics Oy  
Ratastie 2 | FI-01620 Vantaa, Finland  
Phone office +358 10 3292 110  
Fax +358 10 3292 531

Area Manager Jari Siuro ([jari.siuro@thermofisher.com](mailto:jari.siuro@thermofisher.com)) or  
Sales & Application Specialist Hannakaisa Jaatinen ([hannakaisa.jaatinen@thermofisher.com](mailto:hannakaisa.jaatinen@thermofisher.com)).