

Urgent Field Safety Notice

SBN-RDS-CoreLab-2021-003



RDS/Core Lab /Clin.Chem.
Version1
April 2021

Iron Gen.2: throughput dependent signal drifts on cobas c 311, cobas c 501/502 and COBAS INTEGRA® 400 plus

Product Name	Iron Gen.2 (IRON2)	
System	cobas c 311 cobas c 501 cobas c 502 COBAS INTEGRA® 400 plus analyzer	
GMMI / Part No	Iron Gen.2 (IRON2)	03183696122
Device Identifier		
Production Identifier (Product name/Product code)	Lot independent	
SW Version	n/a	
Type of Action	Field Safety Corrective Action	

Dear Valued Customer,

Description of Situation

Several customer complaints were received regarding the increased recovery of controls and discrepant elevated results for the IRON2 on **cobas c 311/501/502** and on COBAS INTEGRA 400 plus (**cobas c** pack).

No allegation of an adverse event has been made.

Internal investigations confirmed the issue and revealed a systematic sample drift up to +4.7 µmol/L absolute for IRON2 over the entire measuring range. The bias increases with the number of tests performed from one **cobas c** pack without further calibration. The first measurements are not affected while the last sample can exhibit the maximal observed bias.

The magnitude of the effect depends on multiple factors of the laboratory's routine (time, analyzer throughput, IRON2 throughput, calibration intervals). The effect is not linked to the on board time.

Optimal hardware and maintenance status of the module can reduce the risk of the occurrence of the issue. Optimizing piercer, reagent probe, reagent rotor adjustment as well as outside wash adjustment and gear pump pressure adjustment also mitigate the issue. Iron abraded from the reagent probes caused by the screw caps of other **cobas c** packs used in parallel to IRON2 leads to iron contamination of the IRON2 reagents resulting in a positive bias.

Iron Gen.2: throughput dependent signal drifts on cobas c 311, cobas c 501/502 and COBAS INTEGRA[®] 400 plus



Only IRON2 in the **cobas c** pack is affected.

cobas c pack large (used for **cobas c** 701/702, uncapped) and **cobas c** pack green (**cobas c** 303/503, different cap materials) are not affected.

cobas c 111 (uncapped) is not affected.

Due to the residual medical risk related to the issue, customers must be informed via FSN-RDS-CoreLab-2021-003.

Actions to be taken by Roche Diagnostics

Immediate workarounds for the customers have been defined. Final solutions are currently under evaluation. Updates will be provided, as more information is available throughout the investigation.

Actions to be taken by the customer/user

The customers are advised to implement the following workarounds depending on their throughput on the respective analyzer:

- Run batch measurements for IRON2 (this workaround is applicable regardless of number on the test determinations per day)
- or
- It is recommended to run a blank calibration with the zero standard using deionized water on the **cobas c** 311/501/502 analyzers or perform a full calibration on COBAS INTEGRA[®] 400 plus after at least every 50 IRON2 determinations out of one **cobas c** pack. Several workaround possibilities are described below separated by
 - Customers running < 50 IRON2 determinations per day out of one **cobas c** pack
 - Customers running ≥ 50 IRON2 determinations per day out of one **cobas c** pack

For technical details with respect to different analyzers, please refer to the instructions attached to the FSN-RDS-CoreLab-2021-003.

Communication of this Field Safety Notice (if appropriate)

This notice must be passed on to all those who need to be aware within your organization where the devices have been distributed/supplied (if appropriate).

Please transfer this notice to other organizations/individuals on which this action has an impact.

Please maintain awareness of this notice and resulting action for an appropriate period to ensure the effectiveness of the corrective action.

Iron Gen.2: throughput dependent signal drifts on cobas c 311, cobas c 501/502 and COBAS INTEGRA[®] 400 plus



The following statement is mandatory in FSNs for EEA countries but is not required for the rest of the World:

Include if applicable: The undersigned confirms that this notice has been notified to the appropriate Regulatory Agency.

We apologize for any inconvenience this may cause and hope for your understanding and your support.

<closing salutations>,

Contact Details

To be completed locally:

Name

Title

Company Name

Address

Tel. +xx-xxx-xxxx xxxx

Email name@roche.com